Approved For Release 2000/08/28 : CIA-RDP66B00664R000300030031-1

CLASSIFIED MESSAGE

SECRET

ROUTING

| | | | |
|---|---|---|---|
| 1 | | 4 | |
| 2 | | 5 | |
| 3 | | 6 | |

0415Z 27 SEP 63

DIRECTOR

25X1A

[redacted]

ACTION: ops 1-7

INFO :

PRIORITY

TOR: 0130Z 27 SEP 63

IN 92942

~~25X1A~~

[redacted]

IDEALIST [redacted] 25X1A

A. [redacted] 25X1A

B. B/10,676/[redacted] 25X1A

C. HTA-2/D-19/4/75

D. 2.18/2.02

E. 9R/8402/234-3-5-3

9L/8402/225-9-5-4-3

F. (1) GOOD

(2) FAIR

(3) GOOD

(4) GOOD

(5) GOOD

(6) GOOD - OVERLAP FRAME 3049

(7) CLEAR

G. TAKE RECEIVED 26/0640 IN STEEL BOX. ALL TAKE REVIEWED. WRINKLES AND TEARS CAUSED BY MALFUNCTION IN HTA-2 SQUEEZEES. WRINKLES IN FRAME NBRS. 005-016R, 028R, 045-46R, 228-231R, 1109-

SECRET

GROUP 1
Excluded from automatic downgrading and declassification

Approved For Release 2000/08/28 : CIA-RDP66B00664R000300030031-1
REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED.

Copy No.

Approved For Release 2000/08/28 : CIA-RDP66B00664R000300030031-1



1118R. TEARS IN 365-366L, 365R. STATIC MARKS 005L AND 1053-55R. MACHINE SCRATCHES 1940-43L, 1949-50L. OUT OF FOCUS FRAMES AT MODE CHANGE. MFG. SPLICES 0000R, 650L, 3176L. PLUS DENSITY SPOTS 1090R, 1095R, 1104R. EMULSION DEFECTS 1098, 1105, 1150, 1152, 1167, 1175, 1259, 1265, 1299, 1304, 1340-47, 1354-56, 1378, 1428, 1555, 1559, 1562-63, 3469, 3472-74, 3544-45, 3553, 3565 ALL R SIDE 2249L, 2470L. MINUS DENSITY SPOTS 005-015L, 21152R 1175R, 2015-17R, 2078R. ORIGINAL STILL BEING USED TO ACCOMPLISH DUPLICATING REQUIREMENTS.

K. HQS COURIER APPROXIMATLY 29/1200Z.

END OF MESSAGE

Approved For Release 2000/08/28 : CIA-RDP66B00664R000300030031-1